

## Site Visit Record

Site Name: <i>Church Lane</i>	Site Number: <i>173</i>
Date: <i>27/3/96</i>	Time: _____
Contact at Site: _____	

**CHECK LIST:-**

AMENITY			OBSERVED ACTIVITIES		
Item	Satisfactory	Not Satisfactory	Item	Satisfactory	Not Satisfactory
Noise			Extraction		
Dust			Infilling		
Mud & highway			Transfer		
Litter			Concrete Crushing/		
Rights of Way			Screening		
Waste Type			Restoration Works - Sub-soiling Top-soiling		

**OTHER NOTES:-**

*Site is fully restored; one part used for horses, the more easterly site is disused scrubland, with some horse jumps. Three small piles of soil remain at the entrance to the site from Spring Walk.*

Name: *Howard Simpson*

